This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


Figure 1




1 2 11

Figure 2A

1/200




50 Forme 2B



FIBZC

11 8 %



Support a polishing number on a fluid bearing between a first end
of the member and a second end of the member the fluid bearing including a curved portion at which axis of travel of the member changes from a first axis to a second axis

Move the member to polish the work piece


320

advance the polishing member of polishing member and a second axis

330

F16 3

Figure 4



6911

Supply a length of member from a supply structure coupled to a slide ~510 Pereire a length of the member in a receive member coupled to the 520 Slide member Support the member on a fluid bearing between the supply structurand the receive structure, the fluid brainly including a curred portion at which axis of travel of the changes from a first axis to a second axis ~530 Move the slide member bi-directionally to create a bi-directional 1-540 movement of the member within a polishing area to polish the workpea advance the polishing member

F165

7 of 11

Figure 6A

612

612

612

613

615

610

620

620

620


620


620

620

Figure 63 . 645.

Forme 7A






120 121

Figure 7C

1000 11

200 V



Figur 8